EXHIBIT 9

OMB Control No.: 2127-0004 Part 573 Safety Recall Report 22V-346

Manufacturer Name: Ford Motor Company

Submission Date: MAY 17, 2022 NHTSA Recall No.: 22V-346 Manufacturer Recall No.: 22S36



Manufacturer Information:

Manufacturer Name: Ford Motor Company

Address: 330 Town Center Drive

Suite 500 Dearborn MI 48126-2738

Company phone: 1-866-436-7332

Population:

Number of potentially involved: 39,013 Estimated percentage with defect: 1 %

Vehicle Information:

Vehicle 1: 2021-2021 Ford Expedition

Vehicle Type: LIGHT VEHICLES

Body Style: SUV Power Train: NR

Descriptive Information: Affected vehicles were built between December 1, 2020 and April 30, 2021.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service

Information System (OASIS) database.

32,711 Expeditions are affected.

Production Dates: DEC 01, 2020 - APR 30, 2021

VIN Range 1: Begin: NR End: NR Not sequential

Case 4.22-cv-11244-SDK-DRG ECF No. 1-10, PageID.139 Filed 06/07/22 Page 3 of 5 Part 573 Safety Recall Report 22V-346 P

Page 2

Vehicle 2: 2021-2021 Lincoln Navigator

Vehicle Type: LIGHT VEHICLES

Body Style: SUV Power Train: NR

Descriptive Information: Affected vehicles were built between December 1, 2020 and April 30, 2021.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service

Information System (OASIS) database.

6,302 Navigators are affected.

Production Dates: DEC 01, 2020 - APR 30, 2021

NR End: NR VIN Range 1 : Begin :

Not sequential

Description of Defect:

Description of the Defect: Ford Motor Company has decided that a defect which relates to motor vehicle

safety exists in certain 2021 model year Ford Expedition and Lincoln Navigator vehicles built between December 01, 2020 and April 30, 2021. Certain vehicles built during this time frame may pose a risk of underhood fire, including while

the vehicle is parked and off.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Risk of underhood fire, including while the vehicle is parked and off.

Description of the Cause: Ford Motor Company is currently investigating the cause of this condition.

Identification of Any Warning Some customers have reported a burning smell and smoke from the front

that can Occur: passenger engine compartment while driving.

Involved Components:

Component Name 1: NR Component Description: NR

Component Part Number: NR

The information contained in this report was submitted pursuant to 49 CFR §573

Case 4.22-cv-11244-SDK-DRG ECF No. 1-10, PageID.140 Filed 06/07/22 Page 4 of 5 Part 573 Safety Recall Report 22V-346 P

Page 3

Supplier Identification:

Component Manufacturer

Name: Ford Motor Company Address: One American Road

Dearborn Michigan 48126

Country: United States

Chronology:

Chronology attached

Description of Remedy:

Description of Remedy Program: Owners of vehicles produced from December 1, 2020 - April 30, 2021 will

be notified by mail and instructed to park their vehicle outside and away from structures and other vehicles due to the risk of unattended vehicle fire. Owners will also be informed that Ford's investigation is ongoing and

that they will be contacted when further information is available.

Ford provided the general reimbursement plan for the cost of remedies

paid for by vehicle

owners prior to notification of a safety recall in May 2021. The ending date

for reimbursement

eligibility is estimated to be June 13, 2022.

Ford will forward a copy of the notification letters to dealers to the agency

when available.

How Remedy Component Differs Not applicable at this time

from Recalled Component:

Identify How/When Recall Condition Not applicable at this time

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: Notification to dealers is expected to occur on May 19, 2022. Mailing of

owner notification letters is expected to begin May 23, 2022 and is

expected to be completed by June 3, 2022.

Planned Dealer Notification Date: MAY 19, 2022 - MAY 19, 2022

Planned Owner Notification Date: MAY 23, 2022 - JUN 03, 2022

Case 4.22-cv-11244-SDK-DRG ECF No. 1-10, Pagetb art 573 Safety Recall Report	22V-346	Page 4
* NR - Not Reported		

The information contained in this report was submitted pursuant to 49 CFR $\S573$